


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>UKAS INSPECTION</p> <p>0278</p> <p>Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	<p>VEGA Environmental Consultants Ltd</p> <p>Issue No: 014 Issue date: 17 July 2019</p>	
	<p>Church Buildings Station Road Seaton Delaval Whitley Bay Tyne and Wear NE25 0PT</p>	<p>Contact: Mr E Brown Tel: +44 (0)191-298 0198 Fax: +44 (0)191-298 0199 E-Mail: edbrown@vegaec.co.uk Website: www.vegaec.co.uk</p>
<p>Inspection performed at/from the locations specified below</p>		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
<p>Address Church Buildings Station Road Seaton Delaval Whitley Bay Tyne and Wear NE25 0PT</p> <p>Local contact Mr E Brown Tel: +44 (0)191 298 0198 Fax: +44 (0)191 298 0199 Email: edbrown@vegaec.co.uk Website: www.vegaec.co.uk</p>	<p><u>Asbestos:</u> Surveying</p>	A
<p>Address Unit 49 Flexspace Business Centre Earls Road Industrial Estate Earls Road Grangemouth East Stirlingshire FK3 4UU</p> <p>Local contact Mr David Bryce Email: DavidBryce@vegaec.co.uk Website: www.vegaec.co.uk</p>	<p><u>Asbestos:</u> Surveying</p>	B



0278
Type C
Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

VEGA Environmental Consultants Ltd
Issue No: 014 Issue date: 17 July 2019

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises	Management survey: Domestic premises Commercial premises Industrial premises	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012) Documented In-House Procedure ASB/6	A, B A A
	Refurbishment survey: Domestic premises Commercial premises Industrial premises	Documented In-House Procedure ASB/6	A, B A A
	Demolition survey: Domestic premises Commercial premises Industrial premises	Documented In-House Procedure ASB/6	A A A
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method ASB/6 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B
	Priority assessment (domestic, commercial & industrial premises)	Documented In-House procedure ASB/6 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appendix 3 of HSG 227 (2004))	A, B
	END		