


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 0278 Type C Inspection Body Accredited to ISO/IEC 17020:2012	VEGA Environmental Consultants Ltd	
	Issue No: 013 Issue date: 08 May 2018	
	Church Buildings Station Road Seaton Delaval Whitley Bay Tyne and Wear NE25 0PT	Contact: Mr E Brown Tel: +44 (0)191-298 0198 Fax: +44 (0)191-298 0199 E-Mail: edbrown@vegaec.co.uk Website: www.vegaec.co.uk
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
Address Church Buildings Station Road Seaton Delaval Whitley Bay Tyne and Wear NE25 0PT Local contact Mr E Brown Tel: +44 (0)191 298 0198 Fax: +44 (0)191 298 0199 Email: edbrown@vegaec.co.uk Website: www.vegaec.co.uk	<u>Asbestos:</u> Surveying	A
Address Unit 49 Flexspace Business Centre Earls Road Industrial Estate Earls Road Grangemouth East Stirlingshire FK3 4UU Local contact Mr Craig Campbell Email: CraigC@vegaec.co.uk Website: www.vegaec.co.uk	<u>Asbestos:</u> Surveying	B



0278
Type C
Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

VEGA Environmental Consultants Ltd
Issue No: 013 Issue date: 08 May 2018

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises	Management survey: Domestic premises Commercial premises Industrial premises	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012) Documented In-House Procedure ASB/6	A, B A A
	Refurbishment survey: Domestic premises Commercial premises Industrial premises	Documented In-House Procedure ASB/6	A, B A A
	Demolition survey: Domestic premises Commercial premises Industrial premises	Documented In-House Procedure ASB/6	A A A
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method ASB/6 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B
	Priority assessment (domestic, commercial & industrial premises)	Documented In-House procedure ASB/6 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appendix 3 of HSG 227 (2004))	A, B
	END		